

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
CAL  
34-ELKGR.V,  
1A-

DREW-SHERWOOD FARM, HOUSE  
7927 Elk Grove Boulevard  
Elk Grove vicinity  
Sacramento County  
California

HABS No. CA-2610-A

Ed Andersen, Photographer  
John Snyder, Field Director  
Richard Wyatt, Lardner Architects, Measured Drawings

Exterior Photographs

- HABS-CA-2610-A-1 South façade, view to north from center of Elk Grove Boulevard. Drew-Sherwood Tank House (HABS No. CA-2610-B) visible at left rear of house.
- HABS-CA-2610-A-2 View to west-northwest, showing south façade and east elevation of house.
- HABS-CA-2610-A-3 East elevation, view to west. Drew-Sherwood Tank House (HABS No. CA-2610-B) at right rear.
- HABS-CA-2610-A-4 North elevation, view to south.
- HABS-CA-2610-A-5 North elevation, view to south. Drew-Sherwood Tank House (HABS No. CA-2610-B) at extreme right.
- HABS-CA-2610-A-6 West elevation, view to east. Drew-Sherwood Tank House (HABS No. CA-2610-B) at left, showing west and south elevations.
- HABS-CA-2610-A-7 Detail, east porch, view to south-southwest. This was originally an open porch (note chamfered porch post in center), enclosed at unknown date. Note also 6/6 windows, which appear only here and in north end of second floor.
- HABS-CA-2610-A-8 Detail, typical 2/2 double-hung window with strip cornice. View to west of window in east elevation.

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
CAL  
34-ELKGR.V  
1A-

DREW-SHERWOOD FARM, HOUSE  
7927 Elk Grove Boulevard  
Elk Grove vicinity  
Sacramento County  
California

HABS No. CA-2610-A

Ed Andersen, Photographer  
John Snyder, Field Director  
Richard Wyatt, Lardner Architects, Measured Drawings

Exterior Photographs

- HABS-CA-2610-A-1 South façade, view to north from center of Elk Grove Boulevard. Drew-Sherwood Tank House (HABS No. CA-2610-B) visible at left rear of house.
- HABS-CA-2610-A-2 View to west-northwest, showing south façade and east elevation of house.
- HABS-CA-2610-A-3 East elevation, view to west. Drew-Sherwood Tank House (HABS No. CA-2610-B) at right rear.
- HABS-CA-2610-A-4 North elevation, view to south.
- HABS-CA-2610-A-5 North elevation, view to south. Drew-Sherwood Tank House (HABS No. CA-2610-B) at extreme right.
- HABS-CA-2610-A-6 West elevation, view to east. Drew-Sherwood Tank House (HABS No. CA-2610-B) at left, showing west and south elevations.
- HABS-CA-2610-A-7 Detail, east porch, view to south-southwest. This was originally an open porch (note chamfered porch post in center), enclosed at unknown date. Note also 6/6 windows, which appear only here and in north end of second floor.
- HABS-CA-2610-A-8 Detail, typical 2/2 double-hung window with strip cornice. View to west of window in east elevation.



DREW-SHERWOOD FARM, HOUSE  
HABS No. CA-2610-A  
INDEX TO PHOTOGRAPHS  
(page 2)

HABS-CA-2610-A-9 Detail, capital moulding on corner boards at northwest corner of two-story block, forming corner pilaster. This is the only extant corner board capital.

Interior Photographs

HABS-CA-2610-A-10 Living Room, view to southeast. Note shouldered door and window surrounds.

HABS-CA-2610-A-11 Living Room, view to west. Doorways are, left to right, to Parlor, to stairway, and to Dining Room.

HABS-CA-2610-A-12 Parlor, view to southwest.

HABS-CA-2610-A-13 Southeast first-floor (front) bedroom, view to southeast.

HABS-CA-2610-A-14 Dining Room, view to southeast. Door at right leads to Living Room, door at left leads to short hall leading to southeast (front) bedroom, and window looks out on enclosed east porch.

HABS-CA-2610-A-15 Dining Room, view to northwest. Door at left is to HVAC closet, open door at center is to Bathroom (not photographed), door at right is to Kitchen.

HABS-CA-2610-A-16 Dining Room, view to northeast. Kitchen door is at extreme left, windows look out on enclosed east porch. Note Eastlake-style built-in cabinet, tongue-and-groove wainscot, chair rail.

HABS-CA-2610-A-17 Kitchen, view to south. Door at left enters from enclosed east porch. Dining Room visible through open door at center, with door to Living Room visible in background. Kitchen is highly altered.

HABS-CA-2610-A-18 Kitchen, view to north-northeast. Window looks out on enclosed east porch. Door at left leads to mud room, with laundry beyond that.

HABS-CA-2610-A-19 Upstairs Bedroom, view to south.

HABS-CA-2610-A-20 Upstairs Bedroom, view to north. Stairs enter just to right of right-hand window.

DREW-SHERWOOD FARM, HOUSE  
HABS No. CA-2610-A  
INDEX TO PHOTOGRAPHS  
(page 2)

HABS-CA-2610-A-9 Detail, capital moulding on corner boards at northwest corner of two-story block, forming corner pilaster. This is the only extant corner board capital.

Interior Photographs

HABS-CA-2610-A-10 Living Room, view to southeast. Note shouldered door and window surrounds.

HABS-CA-2610-A-11 Living Room, view to west. Doorways are, left to right, to Parlor, to stairway, and to Dining Room.

HABS-CA-2610-A-12 Parlor, view to southwest.

HABS-CA-2610-A-13 Southeast first-floor (front) bedroom, view to southeast.

HABS-CA-2610-A-14 Dining Room, view to southeast. Door at right leads to Living Room, door at left leads to short hall leading to southeast (front) bedroom, and window looks out on enclosed east porch.

HABS-CA-2610-A-15 Dining Room, view to northwest. Door at left is to HVAC closet, open door at center is to Bathroom (not photographed), door at right is to Kitchen.

HABS-CA-2610-A-16 Dining Room, view to northeast. Kitchen door is at extreme left, windows look out on enclosed east porch. Note Eastlake-style built-in cabinet, tongue-and-groove wainscot, chair rail.

HABS-CA-2610-A-17 Kitchen, view to south. Door at left enters from enclosed east porch. Dining Room visible through open door at center, with door to Living Room visible in background. Kitchen is highly altered.

HABS-CA-2610-A-18 Kitchen, view to north-northeast. Window looks out on enclosed east porch. Door at left leads to mud room, with laundry beyond that.

HABS-CA-2610-A-19 Upstairs Bedroom, view to south.

HABS-CA-2610-A-20 Upstairs Bedroom, view to north. Stairs enter just to right of right-hand window.